Mechanical Properties of Materials

- Engineering stress-strain
- True stress-strain
- Notch effects
- Bending tests
- Impact energy and fracture toughness
- Hardness
- Fatigue
- High temperature properties
- Residual stress

Material Testing






figure 4.1

Engineering Stress-Strain



True Stress-Strain



Notch Effects






Figure 4–8 A notch on the surface of a body results in a sharp increase of stresses: It causes stress concentration.

- K is the stress concentration factor.
- The presence of cracks on the surface or inside the body may severely reduce the tensile stress that a material can withstand with fracture.
- Fracture stress depends on the crack radius and crack depth.
- Fracture stress is also a function of material constant, which need to be determined in repeated tests.





The rupture strength (flexural strength or modulus of rapture) of brittle materials:

• In the three-point test,

$$\sigma_B = \frac{3}{2} \frac{Pl}{bh^2}$$
 or $\sigma_B = \frac{8Pl}{\pi d^3}$


High, more scattered


• In the four-point test,

$$\sigma_{B} = \frac{Pl}{bh^{2}}$$

Low, more consistent

Impact Energy and Fracture Toughness





- Even ductile material suffer brittle fracture under certain conditions, such as notched form, sudden load, and below ductile-to-brittle transition temperature.
- Impact energy measured should be used only as a comparative value.
- One of the aims of manufacturing processes is to prevent the formation of cracks.
- Cracks must be kept in compression during the service of the part.

Hardness


FIGURE 2.12 General characteristics of hardness-testing methods and formulas for calculating hardness. The quantity *P* is the load applied. *Source*: H. W. Hayden, et al., *The Structure and Properties of Materials*, Vol. III (John Wiley & Sons, 1965).

Test	Indenter	Shape of ind Side view	lentation Top view	Load, P	Hardness number
Brinell	10-mm steel or tungsten carbide ball			500 kg 1500 kg 3000 kg	$HB = \frac{2P}{(\pi D) (D - \sqrt{D^2 - d})}$
Vickers	Diamond pyramid		$\prec^{L^{\lambda}}$	1-120 kg	$HV = \frac{1.854P}{L^2}$
Кпоор	Diamond pyramid	L/b = 7.11 $b/t = 4.00$		25g-5kg	$HK = \frac{14.2P}{L^2}$
Rockwell A C D U	Diamond cone			kg 60 150 100	$ \left. \begin{array}{c} HRA \\ HRC \\ HRD \end{array} \right\} = 100 - 500t $
B F G	$\frac{1}{16}$ - in. diameter steel ball	$\frac{1}{1} = mt$	m ()	100 60 150	$ \begin{array}{c c} \text{HRB} \\ \text{HRF} \\ \text{HRG} \\ \end{array} = 130 - 500t $
Е	$\frac{1}{8}$ - in. diameter steel ball	1 计律子		100	HRE

Hardness and Strength

- Studies have shown that (in the same units) the hardness of a coldworked metal is about three times its yield stress (YS), for annealed metals, it is about five times.
- A relationship has been established between the ultimate tensile strength (UTS) and the Brinell hardness (HB) for steels. In SI units the relationship is
 - HB=~(3-3.5) UTS, where UTS and HB are both in MPa.
- For example, a cold-draw bar has a Brinell hardness of HB=190 kg/mm², the tensile strength is
 - UTS= $190/3.5 = 54.28 \text{ kg/mm}^2 = 531.9 \text{ N/mm}^2$

Fatigue



- Fatigue is caused by stresses much smaller than the tensile strength.
- Fatigue failure starts from a microscopic initial defect, such as microcracks, irregular grain boundaries, and impurity inclusions.
- Stress concentration high enough to cause local damage.
- Fatigue process consists of three stages: initiation, fatigue, fast fracture.
- Fatigue failure has a statistical nature

S-N Curves




Figure 8.19 Stress amplitude (S) versus logarithm of the number of cycles to fatigue failure (N) for (a) a material that displays a fatigue limit, and (b) a material that does not display a fatigue limit.

- Shows the stress level S as a function of the number of cycles to failure N.
- For steel, curve level off after N=10⁶ cycles.
- There is a fatigue limit or endurance limit, denoted by S_n.
- Fatigue limit can be calculated based on reliability, size, and surface finish.
- Some idea on number of cycles: N=5000 rpm * 60 min/hr * 24 hr/day * 365 days/yr *10 years =26*10⁹ cycles

The Effect of Manufacturing Processes





figure 4.14


High-Temperature Properties



Homologous temperature

Residual Stresses


• When a part is subjected to deformation that is not uniform throughout, it develops residual stresses. These are stresses that remain within the part after it has been formed and has had all external forces removed.




• Often residual stresses are caused by plastic deformation, because only elastic strain can be recovered and plastic strain cannot be recovered after the external forces are removed.

Effects of Residual Stresses

• Spring back, distortion, etc.





- Increased fatigue strength
 - Shot peening process

Other Properties of Materials

- Physical properties
 - Density
 - Friction
 - Wear
 - Lubrication
 - Electrical properties, magnetic properties
 - Thermal properties
- Chemical properties

ASM Handbooks Metal's Handbook etc.

MatWeb, the **FREE** materials information database with data on **26,412 materials** including metals, plastics, ceramics, and composites.

http://www.matweb.com/