

# **Chapter 6:** **Mechanical Properties II**



## **Outline**

- Elastic recovery during plastic deformation
- Compressive, shear, and torsional deformation
- Hardness
- Variability of material properties
- Design/safety factors

# Concepts of stress and strain


- **Tension tests**
  - engineering stress
  - engineering strain

$$\sigma = \frac{F}{A_0}$$
$$\varepsilon = \frac{l_i - l_0}{l_0} = \frac{\Delta l}{l_0}$$




- **Compression tests**


# Elastic Deformation




Elastic means reversible!




# Plastic Deformation (Metals)



Plastic means permanent!



# Elastic Strain Recovery





Adapted from Fig. 6.17,  
Callister 7e.

# Other Elastic Properties



- Elastic Shear modulus,  $G$ :

$$\tau = G \gamma$$



- Elastic Bulk modulus,  $K$ :

$$P = -K \frac{\Delta V}{V_0}$$



- Special relations for isotropic materials:

$$G = \frac{E}{2(1+\nu)}$$


$$K = \frac{E}{3(1-2\nu)}$$

# Useful Linear Elastic Relationships

- Simple tension:


$$\delta = \frac{FL_o}{EA_o}$$

$$\delta_L = -\nu \frac{Fw_o}{EA_o}$$



- Simple torsion:


$$\alpha = \frac{2ML_o}{\pi r_o^4 G}$$



- Material, geometric, and loading parameters all contribute to deflection.
- Larger elastic moduli minimize elastic deflection.

# Hardness

- Resistance to permanently indenting the surface.
- Large hardness means:
  - resistance to plastic deformation or cracking in compression.
  - better wear properties.



# Hardness: Measurement

- Rockwell
  - No major sample damage
  - Each scale runs to 130 but only useful in range 20-100.
  - Minor load 10 kg
  - Major load 60 (A), 100 (B) & 150 (C) kg
    - A = diamond, B = 1/16 in. ball, C = diamond
- HB = Brinell Hardness
  - $TS \text{ (psia)} = 500 \times HB$
  - $TS \text{ (MPa)} = 3.45 \times HB$

# Hardness: Measurement

Table 6.5 Hardness Testing Techniques

Test	Indenter	Shape of Indentation		Load	Formula for Hardness Number <sup>a</sup>
		Side View	Top View		
Brinell	10-mm sphere of steel or tungsten carbide			$P$	$HB = \frac{2P}{\pi D[D - \sqrt{D^2 - d^2}]}$
Vickers microhardness	Diamond pyramid			$P$	$HV = 1.854P/d_1^2$
Knoop microhardness	Diamond pyramid			$P$	$HK = 14.2P/l^2$
Rockwell and Superficial Rockwell	Diamond cone $\frac{1}{16}, \frac{1}{8}, \frac{1}{4}, \frac{1}{2}$ in. diameter steel spheres			60 kg 100 kg 150 kg 15 kg 30 kg 45 kg	Rockwell Superficial Rockwell

<sup>a</sup> For the hardness formulas given,  $P$  (the applied load) is in kg, while  $D$ ,  $d$ ,  $d_1$ , and  $l$  are all in mm.

**Source:** Adapted from H. W. Hayden, W. G. Moffatt, and J. Wulff, *The Structure and Properties of Materials*, Vol. III, *Mechanical Behavior*. Copyright © 1965 by John Wiley & Sons, New York. Reprinted by permission of John Wiley & Sons, Inc.



# Hardness tests (*continued*)

- **Rockwell and superficial rockwell**
- **20<hardness<100**

**Table 6.5a Rockwell Hardness Scales**

Scale Symbol	Indenter	Major Load (kg)
A	Diamond	60
B	$\frac{1}{16}$ in. ball	100
C	Diamond	150
D	Diamond	100
E	$\frac{1}{8}$ in. ball	100
F	$\frac{1}{16}$ in. ball	60
G	$\frac{1}{16}$ in. ball	150
H	$\frac{1}{8}$ in. ball	60
K	$\frac{1}{8}$ in. ball	150


**Table 6.5b Superficial Rockwell Hardness Scales**

Scale Symbol	Indenter	Major Load (kg)
15N	Diamond	15
30N	Diamond	30
45N	Diamond	45
15T	$\frac{1}{16}$ in. ball	15
30T	$\frac{1}{16}$ in. ball	30
45T	$\frac{1}{16}$ in. ball	45
15W	$\frac{1}{8}$ in. ball	15
30W	$\frac{1}{8}$ in. ball	30
45W	$\frac{1}{8}$ in. ball	45




# Hardness tests

- Brinell: 10-mm sphere of steel or tungsten carbide
- Knoop and Vickers microhardness
- Hardness conversion



# Correlation between hardness and tensile strength

- **Relations between hardness and tensile strength for steel, brass, and cast iron.**
- **For most steels:**  
 $TS \text{ (MPa)} = 3.45 \times HB$   
 $TS \text{ (psi)} = 500 \times HB$



# Example

- Estimate the Brinell and Rockwell hardness for brass





FIGURE 6.12 The stress-strain behavior for the brass specimen



# Errors and Measurements (lab)



Error in a scientific measurement usually does not mean a mistake or blunder. Instead, the terms "error" and "uncertainty" both refer to unavoidable imprecision in measurements.

Error analysis may seem tedious; however, without proper error analysis, no valid scientific conclusions can be drawn.

[http://phys.columbia.edu/  
~tutorial/](http://phys.columbia.edu/~tutorial/)



# Variability in Material Properties

- Elastic modulus is material property
- Critical properties depend largely on sample flaws (defects, etc.). Large sample to sample variability.
- Statistics
  - Mean

$$\bar{x} = \frac{\sum x_n}{n}$$

- Standard Deviation

$$s = \left[ \frac{\sum (x_i - \bar{x})^2}{n-1} \right]^{\frac{1}{2}}$$

where  $n$  is the number of data points





# Example

- Determine the average and standard deviation of tensile strength

Sample Number	Tensile Strength (MPa)
1	520
2	512
3	515
4	522

$$\begin{aligned}\bar{TS} &= \frac{\sum_{i=1}^4 (TS)_i}{4} \\ &= \frac{520 + 512 + 515 + 522}{4} \\ &= 517 \text{ MPa}\end{aligned}$$

$$\begin{aligned}s &= \sqrt{\frac{\sum_{i=1}^4 \{(TS)_i - \bar{TS}\}^2}{4-1}} \\ &= \sqrt{\frac{(520-517)^2 + (512-517)^2 + (515-517)^2 + (522-517)^2}{4-1}} \\ &= 4.6 \text{ MPa}\end{aligned}$$



# Design or Safety Factors

- Design uncertainties mean we do not push the limit.
- Factor of safety,  $N$

$$\sigma_{working} = \frac{\sigma_y}{N}$$

Often  $N$  is  
between  
1.2 and 4

- Example: Calculate a diameter,  $d$ , to ensure that yield does not occur in the 1045 carbon steel rod below. Use a factor of safety of 5.


$$\frac{220,000N}{\pi(d^2 / 4)} = \frac{\sigma_y}{N}$$

5

$$d = 0.067 \text{ m} = 6.7 \text{ cm}$$

1045 plain  
carbon steel:  
 $\sigma_y = 310 \text{ MPa}$   
 $TS = 565 \text{ MPa}$

$$F = 220,000 \text{ N}$$



# Summary

- **Stress** and **strain**: These are size-independent measures of load and displacement, respectively.
- **Elastic** behavior: This reversible behavior often shows a linear relation between stress and strain. To minimize deformation, select a material with a large elastic modulus ( $E$  or  $G$ ).
- **Plastic** behavior: This permanent deformation behavior occurs when the tensile (or compressive) uniaxial stress reaches  $\sigma_y$ .
- **Toughness**: The energy needed to break a unit volume of material.
- **Ductility**: The plastic strain at failure.
- **Hardness**: Resistance to permanently indenting the surface.
- **Safety**: Design uncertainties mean we do not push the limit

