

Chapter 11: Metal Alloys

Applications and Processing

- How are metal alloys classified and how are they used?
- How do properties vary throughout a piece of material that has been quenched, for example?
- How can properties be modified by heat treatment?



How to distribute your efforts on chapter 11

Read Only: 11-1 to 11-6 make sure you think about all the phase transformation we have been looking at while you read about the different kinds of steels and irons.

Study: 11-7 to 11-9 and think about lab V while you do so.




Basic concepts

- **Annealing: a heat treatment**
 - heat up
 - hold for for an extended time period
 - cool
- **Function of annealing:**
 - relieve stress
 - increase softness, ductility and toughness
 - produce specific microstructure




Thermal Processing of Metals

Annealing: Heat to T_{anneal} , then cool slowly.



Heat Treatment




- a) Annealing
- b) Quenching
- c) Tempered Martensite

The figure is a Time-Temperature Transformation (TTT) diagram. The vertical axis represents Temperature (T) in degrees Celsius ($^{\circ}\text{C}$), ranging from 0 to 800. The horizontal axis represents time in seconds (s) on a logarithmic scale, with major ticks at 10^{-1} , 10, 10^3 , and 10^5 . A horizontal orange line at approximately 725°C is labeled T_E . The top region of the plot is shaded light blue and labeled "Austenite (stable)". Several curves are shown: a solid blue curve starting near 780°C and decreasing; a solid red curve forming a nose shape; a solid green curve also forming a nose shape; and dashed black curves representing intermediate transformation levels. Labels "A" and "B" are placed near the curves. On the right side, there are three horizontal bars indicating different transformation stages: "0%", "50%", and "90%". At the bottom left, a red label "b)" points to the start of the red curve. At the bottom right, a blue label "a)" points to the end of the blue curve. A pink bracket on the far right is labeled "c)". In the bottom right corner, there is a circular logo with the letters "VW" and the text "Chapter 11 - 6" below it.




Hardenability--Steels

- Ability to form martensite
- Jominy end quench test to measure hardenability.



Adapted from Fig. 11.11, *Callister 7e*. (Fig. 11.11 adapted from A.G. Guy, *Essentials of Materials Science*, McGraw-Hill Book Company, New York, 1978.)


- Hardness versus distance from the quenched end.



Adapted from Fig. 11.12, *Callister 7e*.




- The cooling rate varies with position.




Hardenability vs Alloy Composition

- Jominy end quench results, $C = 0.4 \text{ wt\% C}$

Adapted from Fig. 11.14, *Callister 7e*.
(Fig. 11.14 adapted from figure furnished courtesy Republic Steel Corporation.)



- "Alloy Steels"
(4140, 4340, 5140, 8640)
--contain Ni, Cr, Mo
 (0.2 to 2wt%)
--these elements shift
 the "nose".
--martensite is easier
 to form.



Quenching Medium & Geometry


- Effect of quenching medium:

Medium	Severity of Quench	Hardness
air	low	low
oil	moderate	moderate
water	high	high

- Effect of geometry:

When surface-to-volume ratio increases:

- cooling rate increases
- hardness increases




Precipitation Hardening

- Particles impede dislocations.
- Ex: Al-Cu system
- Procedure:


- Pt A: solution heat treat (get α solid solution)
- Pt B: quench to room temp.
- Pt C: reheat to nucleate small θ crystals within α crystals.

- Other precipitation systems:

- Cu-Be
- Cu-Sn
- Mg-Al



Adapted from Fig. 11.24, *Callister 7e*. (Fig. 11.24 adapted from J.L. Murray, *International Metals Review* **30**, p.5, 1985.)




Adapted from Fig. 11.22, *Callister 7e*.




Example: 7150-T651 Al alloy

- **Boeing 757**



- **Microstructure: $MgZn_2$ particles**

Callister,
Fig. 11.0(b)



Summary

- Steels: increase *TS*, Hardness (and cost) by adding
 - C (low alloy steels)
 - Cr, V, Ni, Mo, W (high alloy steels)
 - ductility usually decreases w/additions.
- Non-ferrous:
 - Cu, Al, Ti, Mg, Refractory, and noble metals.
- Hardenability
 - increases with alloy content.
- Precipitation hardening
 - effective means to increase strength in Al, Cu, and Mg alloys.