


# Chapter 11: Metal Alloys Applications and Processing

## ISSUES TO ADDRESS...

- How are metal alloys classified and how are they used?
- What are some of the common fabrication techniques?
- How do properties vary throughout a piece of material that has been quenched, for example?
- How can properties be modified by post heat treatment?



# Taxonomy of Metals




Adapted from Fig. 11.1, Callister 7e.

microstructure: ferrite, graphite cementite

Adapted from Fig. 9.24, Callister 7e. (Fig. 9.24 adapted from *Binary Alloy Phase Diagrams*, 2nd ed., Vol. 1, T.B. Massalski (Ed.-in-Chief), ASM International, Materials Park, OH, 1990.)



# Steels



increasing strength, cost, decreasing ductility

Based on data provided in Tables 11.1(b), 11.2(b), 11.3, and 11.4, Callister 7e.



# Ferrous Alloys

Iron containing – Steels - cast irons

Nomenclature AISI & SAE

10xx Plain Carbon Steels

11xx Plain Carbon Steels (resulfurized for machinability)

15xx Mn (10 ~ 20%)

40xx Mo (0.20 ~ 0.30%)

43xx Ni (1.65 - 2.00%), Cr (0.4 - 0.90%), Mo (0.2 - 0.3%)

44xx Mo (0.5%)

where xx is wt% C x 100

example: 1060 steel – plain carbon steel with 0.60 wt% C

Stainless Steel -- >11% Cr



# Cast Iron


- Ferrous alloys with  $> 2.1$  wt% C
  - more commonly 3 - 4.5 wt%C
- low melting (also brittle) so easiest to cast
- Cementite decomposes to ferrite + graphite
$$\text{Fe}_3\text{C} \rightarrow 3 \text{Fe} (\alpha) + \text{C} (\text{graphite})$$
  - generally a slow process



# Fe-C True Equilibrium Diagram

Graphite formation promoted by

- Si > 1 wt%
- slow cooling



Adapted from Fig. 11.2, Callister 7e. (Fig. 11.2 adapted from *Binary Alloy Phase Diagrams*, 2nd ed., Vol. 1, T.B. Massalski (Ed.-in-Chief), ASM International, Materials Park, OH, 1990.)



# Types of Cast Iron

## Gray iron


- graphite flakes
- weak & brittle under tension
- stronger under compression
- excellent vibrational dampening
- wear resistant



Adapted from Fig. 11.3(a) & (b), *Callister 7e*.

## Ductile iron

- add Mg or Ce
- graphite in nodules not flakes
- matrix often pearlite - better ductility



# Types of Cast Iron

## White iron


- <1wt% Si so harder but brittle
- more cementite



Adapted from Fig. 11.3(c) & (d), *Callister 7e*.

## Malleable iron


- heat treat at 800-900°C
- graphite in rosettes
- more ductile






# Production of Cast Iron

Adapted from Fig.11.5,  
Callister 7e.




Reheat: hold at  
 $\sim 700^{\circ}\text{C}$  for 30 + h

Fast cool	Slow cool
$P + G_r$	$\alpha + G_r$



Pearlitic malleable




Ferritic malleable


Fast cool	Moderate	Slow cool
$P + \text{Fe}_3\text{C}$	$P + G_f$	$\alpha + G_f$



White cast iron




Pearlitic gray cast iron




Ferritic gray cast iron

Moderate	Slow cool
$P + G_n$	$\alpha + G_n$



Pearlitic ductile cast iron



Ferritic ductile cast iron

# Limitations of Ferrous Alloys

- 1) Relatively high density
- 2) Relatively low conductivity
- 3) Poor corrosion resistance



# Nonferrous Alloys

## • Cu Alloys

**Brass:** Zn is subst. impurity (costume jewelry, coins, corrosion resistant)

**Bronze:** Sn, Al, Si, Ni are subst. impurity (bushings, landing gear)

**Cu-Be:** precip. hardened for strength

## • Ti Alloys

-lower  $\rho$ : 4.5g/cm<sup>3</sup>  
vs 7.9 for steel  
-reactive at high  $T$   
-space applic.

## NonFerrous Alloys

• **Noble metals**  
-Ag, Au, Pt  
-oxid./corr. resistant

## • Al Alloys

-lower  $\rho$ : 2.7g/cm<sup>3</sup>  
-Cu, Mg, Si, Mn, Zn additions  
-solid sol. or precip. strengthened (struct. aircraft parts & packaging)

## • Mg Alloys

-very low  $\rho$ : 1.7g/cm<sup>3</sup>  
-ignites easily  
-aircraft, missiles

## • Refractory metals

-high melting  $T$   
-Nb, Mo, W, Ta



# Metal Fabrication

- How do we fabricate metals?
  - Blacksmith - hammer (forged)
  - Molding - cast
- Forming Operations
  - Rough stock formed to final shape

## Hot working

- $T$  high enough for recrystallization
- Larger deformations

vs.

## Cold working

- well below  $T_m$
- work hardening
- smaller deformations




# Metal Fabrication Methods - I

## FORMING


## CASTING

## JOINING

- Forging (Hammering; Stamping) (wrenches, crankshafts)




- Drawing (rods, wire, tubing)




die must be well lubricated & clean

- Rolling (Hot or Cold Rolling) (I-beams, rails, sheet & plate)



Adapted from Fig. 11.8, Callister 7e.

- Extrusion (rods, tubing)



ductile metals, e.g. Cu, Al (hot)



# Metal Fabrication Methods - II



- **Casting**- mold is filled with metal
  - metal melted in furnace, perhaps alloying elements added. Then **cast** in a mold
  - most common, cheapest method
  - gives good production of shapes
  - weaker products, internal defects
  - good option for brittle materials



# Metal Fabrication Methods - II


FORMING

CASTING

JOINING

- Sand Casting

(large parts, e.g.,  
auto engine blocks)




- trying to hold something that is hot
- what will withstand  $>1600^{\circ}\text{C}$ ?
- cheap - easy to mold => sand!!!
- pack sand around form (pattern) of desired shape

# Metal Fabrication Methods - II



- **Sand Casting**


(large parts, e.g., auto engine blocks)



- **Investment Casting**

(low volume, complex shapes e.g., jewelry, turbine blades)

plaster die formed around wax prototype



## Investment Casting

- pattern is made from paraffin.
- mold made by encasing in plaster of paris
- melt the wax & the hollow mold is left
- pour in metal





# Metal Fabrication Methods - II


FORMING

CASTING

JOINING

- Sand Casting


(large parts, e.g., auto engine blocks)



- Investment Casting


(low volume, complex shapes e.g., jewelry, turbine blades)

plaster die formed around wax prototype




- Die Casting

(high volume, low T alloys)



- Continuous Casting

(simple slab shapes)




# Metal Fabrication Methods - III

FORMING


CASTING

JOINING

- Powder Metallurgy  
(materials w/low ductility)



- Welding  
(when one large part is impractical)




- Heat affected zone:  
(region in which the microstructure has been changed).

Adapted from Fig. 11.9, *Callister 7e*.  
(Fig. 11.9 from *Iron Castings Handbook*, C.F. Walton and T.J. Opar (Ed.), 1981.)



# Thermal Processing of Metals


**Annealing:** Heat to  $T_{\text{anneal}}$ , then cool slowly.



# Heat Treatments


- a) Annealing
- b) Quenching
- c) Tempered Martensite

Adapted from Fig. 10.22, Callister 7e.




# Hardenability--Steels

- Ability to form martensite
- Jominy end quench test to measure hardenability.



Adapted from Fig. 11.11, *Callister 7e*. (Fig. 11.11 adapted from A.G. Guy, *Essentials of Materials Science*, McGraw-Hill Book Company, New York, 1978.)


- Hardness versus distance from the quenched end.



Adapted from Fig. 11.12, *Callister 7e*.

# Why Hardness Changes W/Position

- The cooling rate varies with position.



Adapted from Fig. 11.13, *Callister 7e*.  
(Fig. 11.13 adapted from H. Boyer (Ed.)  
*Atlas of Isothermal Transformation and  
Cooling Transformation Diagrams*,  
American Society for Metals, 1977, p.  
376.)



# Quenching Medium & Geometry


- Effect of quenching medium:

Medium	Severity of Quench	Hardness
air	low	low
oil	moderate	moderate
water	high	high

- Effect of geometry:


When surface-to-volume ratio increases:

- cooling rate increases
- hardness increases



# Precipitation Hardening


- Particles impede dislocations.
- Ex: Al-Cu system
- Procedure:
  - Pt A: solution heat treat (get  $\alpha$  solid solution)
  - Pt B: quench to room temp.
  - Pt C: reheat to nucleate small  $\theta$  crystals within  $\alpha$  crystals.



Adapted from Fig. 11.24, *Callister 7e*. (Fig. 11.24 adapted from J.L. Murray, *International Metals Review* 30, p.5, 1985.)

- Other precipitation systems:

- Cu-Be
- Cu-Sn
- Mg-Al







Adapted from Fig. 11.22, *Callister 7e*.







# Precipitation Hardening



# Precipitate Effect on $TS$ , $\%EL$

- 2014 Al Alloy:
- $TS$  peaks with precipitation time.
- Increasing  $T$  accelerates process.
- $\%EL$  reaches minimum with precipitation time.



# Summary

- Steels: increase  $TS$ , Hardness (and cost) by adding
  - C (low alloy steels)
  - Cr, V, Ni, Mo, W (high alloy steels)
  - ductility usually decreases w/additions.
- Non-ferrous:
  - Cu, Al, Ti, Mg, Refractory, and noble metals.
- Fabrication techniques:
  - forming, casting, joining.
- Hardenability
  - increases with alloy content.
- Precipitation hardening
  - effective means to increase strength in Al, Cu, and Mg alloys.

