

### Taxonomy of metals

#### Metal Alloys



#### Steels



2

#### Nomenclature for steel

```
Nomenclature AISI & SAE
  10xx
         Plain Carbon Steels
         Plain Carbon Steels (resulfurized for machinability)
  11xx
  15xx
         Mn (10 \sim 20\%)
  40xx
         Mo (0.20 \sim 0.30\%)
         Ni (1.65 - 2.00%), Cr (0.4 - 0.90%), Mo (0.2 - 0.3%)
  43xx
  44xx
         Mo (0.5%)
where xx is wt% C x 100
   example: 1060 steel – plain carbon steel with 0.60 wt% C
Stainless Steel -- >11% Cr
```


### Cast iron

- Ferrous alloys with > 2.1 wt% Cmore commonly 3 4.5 wt%C
- •low melting (also brittle) so easiest to cast

•Cementite decomposes to ferrite + graphite Fe<sub>3</sub>C → 3 Fe (α) + C (graphite)

Decomposition promoted by Si

Adapted from Fig. 11.2, Callister 7e. (Fig. 11.2 adapted from Binary Alloy Phase Diagrams, 2nd ed., Vol. 1, T.B. Massalski (Ed.-in-Chief), ASM International, Materials Park, OH, 1990.)




# Types of cast iron

#### Gray iron


- graphite flakes
- weak & brittle under tension
- stronger under compression
- excellent vibrational dampening
- wear resistant

#### Ductile iron

- add Mg or Ce
- graphite in nodules not flakes
- matrix often pearlite better ductility



Adapted from Fig. 11.3(a) & (b), Callister 7e.



# Types of cast iron

#### White iron


- •<1wt% Si so harder but brittle
- more cementite

#### Malleable iron


- •heat treat at 800-900°C
- •graphite in rosettes
- more ductile



Adapted from Fig. 11.3(c) & (d), Callister 7e.



#### Production of cast iron



# Other alloys

Cu Alloys

Brass: Zn is subst. impurity (costume jewelry, coins, corrosion resistant)

Bronze: Sn, Al, Si, Ni are

subst. impurity (bushings, landing gear)

Cu-Be

precip. hardened for strength

Ti Alloys

-lower  $\rho$ : 4.5g/cm<sup>3</sup>

vs 7.9 for steel

-reactive at high T

-space applic.

Al Alloys

-lower  $\rho$ : 2.7g/cm<sup>3</sup>

-Cu, Mg, Si, Mn, Zn additions

-solid sol. or precip.

strengthened (struct.

aircraft parts

& packaging)

Mg Alloys

-very low ρ: 1.7g/cm<sup>3</sup>

-ignites easily

-aircraft, missiles

Refractory metals

-high melting T

-Nb, Mo, W, Ta

Noble metals

NonFerrous

Alloys


-Ag, Au, Pt

-oxid./corr. resistant


#### Metal fabrication methods 1



Forging (Hammering; Stamping) •
 (wrenches, crankshafts)
 force




Drawing (rods, wire, tubing)




die must be well lubricated & clean

 Rolling (Hot or Cold Rolling) (I-beams, rails, sheet & plate)



ductile metals, e.g. Cu, Al (hot)9

#### Metal fabrication methods 2



Sand Casting

 (large parts, e.g.,
 auto engine blocks)


Sand Sand

Investment Casting

(low volume, complex shapes e.g., jewelry, turbine blades)



 Die Casting (high volume, low T alloys)



 Continuous Casting (simple slab shapes)



#### Metal fabrication methods 3




 Powder Metallurgy (materials w/low ductility)

heat
area
contact
densify

point contact
at low T

densification
by diffusion at
higher T

 Welding (when one large part is impractical)



Heat affected zone:

 (region in which the microstructure has been changed).


11.9, Callister 7e. (Fig. 11.9 from Iron Castings Handbook, C.F. Walton and T.J. Opar (Ed.), 1981.)

## Thermal processing of metals

## Annealing: Heat to $T_{anneal}$ , then cool slowly.


 Stress Relief: Reduce Spheroidize (steels): Make very soft steels for stress caused by: good machining. Heat just -plastic deformation -nonuniform cooling below  $T_F$  & hold for -phase transform. 15-25 h. • Full Anneal (steels): Types of Make soft steels for Annealing good forming by heating to get  $\gamma$ , then cool in furnace to get coarse P. Process Anneal Negate effect of Normalize (steels): cold working by Deform steel with large (recovery/ grains, then normalize recrystallization) to make grains small.


### Heat treatments



## Precipitation hardening

- Particles impede dislocations.
- Ex: Al-Cu system
- · Procedure:
  - --Pt A: solution heat treat (get  $\alpha$  solid solution)
  - --Pt B: quench to room temp.
  - --Pt C: reheat to nucleate small  $\theta$  crystals within  $\alpha$  crystals.
- Other precipitation systems:






Adapted from Fig. 11.24, *Callister 7e*. (Fig. 11.24 adapted from J.L. Murray, *International Metals Review* **30**, p.5, 1985.)

## Precipitation hardening

- 2014 Al Alloy:
- TS peaks with precipitation time.
- Increasing *T* accelerates process.


 %EL reaches minimum with precipitation time.



Adapted from Fig. 11.27 (a) and (b), *Callister 7e*. (Fig. 11.27 adapted from *Metals Handbook: Properties and Selection: Nonferrous Alloys and Pure Metals*, Vol. 2, 9th ed., H. Baker (Managing Ed.), American Society for Metals, 1979. p. 41.)

#### Ceramics


- Bonding:
  - -- Mostly ionic, some covalent.
  - -- % ionic character increases with difference in electronegativity.
- Large vs small ionic bond character:



Adapted from Fig. 2.7, *Callister 7e.* (Fig. 2.7 is adapted from Linus Pauling, *The Nature of the Chemical Bond*, 3rd edition, Copyright 1939 and 1940, 3rd edition. Copyright 1960 by Cornell University.

### Silicate Ceramics


Most common elements on earth are Si & O



- SiO<sub>2</sub> (silica) structures are quartz, crystobalite, & tridymite
- The strong Si-O bond leads to a strong, high melting material (1710°C)


## Amorphous silica

- Silica gels amorphous SiO<sub>2</sub>
  - Si<sup>4+</sup> and O<sup>2-</sup> not in well-ordered lattice
  - Charge balanced by H<sup>+</sup> (to form OH<sup>-</sup>) at "dangling" bonds
    - very high surface area > 200 m<sup>2</sup>/g
  - SiO<sub>2</sub> is quite stable, therefore unreactive
    - makes good catalyst support



### **Silicates**


 Combine SiO<sub>4</sub><sup>4-</sup> tetrahedra by having them share corners, edges, or faces



 Cations such as Ca<sup>2+</sup>, Mg<sup>2+</sup>, & Al<sup>3+</sup> act to neutralize & provide ionic bonding


# Layered silicates

- Layered silicates (clay silicates)
  - SiO<sub>4</sub> tetrahedra connected together to form 2-D plane




 $(Si_2O_5)^{2-}$ 

 Therefore, cations are required to balance charge



## Layered silicates


Kaolinite clay alternates (Si<sub>2</sub>O<sub>5</sub>)<sup>2-</sup> layer with Al<sub>2</sub>(OH)<sub>4</sub><sup>2+</sup> layer



Note: these sheets loosely bound by van der Waal's forces 21

#### Carbon forms


- Carbon black amorphous surface area ca. 1000 m²/g
- Diamond
  - tetrahedral carbon
    - hard no good slip planes
    - brittle can cut it
  - large diamonds jewelry
  - small diamonds
    - often man made used for cutting tools and polishing
  - diamond films
    - hard surface coat tools, medical devices, etc.



Adapted from Fig. 12.15, Callister 7e.

### Carbon forms

layer structure – aromatic layers




- weak van der Waal's forces between layers
- planes slide easily, good lubricant

### Carbon forms


#### Fullerenes or carbon nanotubes

- •wrap the graphite sheet by curving into ball or tube
- •Buckminister fullerenes
  - •Like a soccer ball  $C_{60}$  also  $C_{70}$  + others



### **Defects**

- Frenkel Defect
  - --a cation is out of place.
- Shottky Defect
  - --a paired set of cation and anion vacancies.



Adapted from Fig. 12.21, *Callister 7e.* (Fig. 12.21 is from W.G. Moffatt, G.W. Pearsall, and J. Wulff, *The Structure and Properties of Materials*, Vol. 1, *Structure*, John Wiley and Sons, Inc., p. 78.)

Equilibrium concentration of defects


$$\sim e^{-Q_D/kT}$$

### **Impurities**


• Impurities must also satisfy charge balance = Electroneutrality


• Ex: NaCl Na + OCI -


Substitutional cation impurity



Substitutional anion impurity









# Ceramic phase diagrams

#### MgO-Al<sub>2</sub>O<sub>3</sub> diagram:




### Measuring the elastic modulus

- Room *T* behavior is usually elastic, with brittle failure.
- 3-Point Bend Testing often used.
  - --tensile tests are difficult for brittle materials.




• Determine elastic modulus according to:



$$E = \frac{F}{\delta} \frac{L^3}{4bd^3} = \frac{F}{\delta} \frac{L^3}{12\pi R^4}$$
rect. cross cross section section

### Measuring strengths

• 3-point bend test to measure room *T* strength.



• Flexural strength:

 $\sigma_{fs} = \frac{1.5F_fL}{bd^2} = \frac{F_fL}{\pi R^3}$   $F_f \uparrow F \downarrow \delta$ 

• Typ. values:

Material	$\sigma_{fS}(MPa)$	E(GPa)
Si nitride	250-1000	304
Si carbide	100-820	345
Al oxide	275-700	393
glass (soda)	69	69

Data from Table 12.5, Callister 7e.