



The iron-iron carbide (Fe- Fe_3C) phase diagram


- Ferrite- α -BCC, low C solubility(0.022%wt), magnetic
- Austenite- γ -FCC, high C solubility(2.14%wt), nonmagnetic
- Ferrite- δ -BCC
- Cementite (Fe_3C)
- Eutectic, peritectic, eutectoid
- Iron, ferrite ($\text{C}<0.008\text{wt}\%$)
- Stainless steel, $\alpha+\text{Fe}_3\text{C}$ (0.008-2.14wt%)




Microstructures of iron



Interstitial sites of FCC




Interstitial sites of BCC





Microstructure in iron-carbon alloys

□ Eutectic-pearlite




Hypoeutectoid alloys

□ Hypoeutectoid steel: has a carbon concentration less than the eutectoid



Hypereutectoid alloys

- Hypereutectoid steel: has a carbon content greater than the eutectoid



Example: Phase Equilibria

For a 99.6 wt% Fe-0.40 wt% C at a temperature just below the eutectoid, determine the following

- composition of Fe_3C and ferrite (α)
- the amount of carbide (cementite) in grams that forms per 100 g of steel
- the amount of pearlite and proeutectoid ferrite (α)

Phase Equilibria

Solution: a) composition of Fe_3C and ferrite (α)

b) the amount of carbide (cementite) in grams that forms per 100 g of steel

$$C_o = 0.40 \text{ wt% C}$$

$$C_\alpha = 0.022 \text{ wt% C}$$


$$C_{\text{Fe}_3\text{C}} = 6.70 \text{ wt% C}$$

$$\frac{\text{Fe}_3\text{C}}{\text{Fe}_3\text{C} + \alpha} = \frac{C_o - C_\alpha}{C_{\text{Fe}_3\text{C}} - C_\alpha} \times 100$$

$$= \frac{0.4 - 0.022}{6.7 - 0.022} \times 100 = 5.7 \text{ g}$$

$$\boxed{\text{Fe}_3\text{C} = 5.7 \text{ g}}$$

$$\alpha = 94.3 \text{ g}$$



Phase Equilibria

c. the amount of pearlite and proeutectoid ferrite (α)

note: amount of pearlite = amount of γ just above T_E

$$C_o = 0.40 \text{ wt% C}$$


$$C_\alpha = 0.022 \text{ wt% C}$$

$$C_{\text{pearlite}} = C_\gamma = 0.76 \text{ wt% C}$$

$$\frac{\gamma}{\gamma + \alpha} = \frac{C_o - C_\alpha}{C_\gamma - C_\alpha} \times 100 = 51.2 \text{ g}$$


$$\boxed{\text{pearlite} = 51.2 \text{ g}}$$

$$\text{proeutectoid } \alpha = 48.8 \text{ g}$$




The influence of other alloying elements

- $T_{\text{eutectoid}}$ changes:



- $C_{\text{eutectoid}}$ changes:



Review Fe-C phase diagram


- 2 important points

-Eutectic (A):


$$L \Rightarrow \gamma + \text{Fe}_3\text{C}$$

-Eutectoid (B):

$$\gamma \Rightarrow \alpha + \text{Fe}_3\text{C}$$



Result: Pearlite = alternating layers of α and Fe_3C phases



Summary

- Phase diagrams are useful tools to determine:
 - the number and types of phases,
 - the wt% of each phase,
 - and the composition of each phasefor a given T and composition of the system.
- Alloying to produce a solid solution usually
 - increases the tensile strength (TS)
 - decreases the ductility.
- Binary eutectics and binary eutectoids allow for a range of microstructures.