
# Chapter 10 Phase transformation in metals Basic concepts The kinetics of solid-state reactions Isothermal transformation diagrams Mechanical behavior of iron-carbon alloys

### Basic concepts

- ☐ Phase transformation takes time to occur
- ☐ Types of phase transformation

# The kinetics of solid-state reactions

### ☐ Fraction of transformation depends on T




Logarithm of heating time, t

Growth

### The kinetics of solid-state reactions (continue)

### ☐ Transformation rate depends on T



r often small: equil. not possible!

Callister, Fig. 10.2

### Isothermal transformation diagrams Transformation ends Transformation temperature 675°C ☐ Iron-iron carbide eutectoid reaction Transformation Eutectoid temperature Austenite (stable) Temperature (°C) 50% Completion curve 1000 500 800 400

10<sup>2</sup>

10<sup>3</sup> Time (s)

## Pearlite morphology

