


Chapter 6: Mechanical properties of metals

Outline

- Elastic recovery during plastic deformation
- Hardness
- Variability of material properties
- Design/safety factors

Elastic recovery during plastic deformation


- Schematic tensile stress-strain diagram showing elastic strain recovery



Ductility, %EL

- Plastic tensile strain at failure:

$$\%EL = \frac{L_f - L_o}{L_o} \times 100$$



- Another ductility measure:


$$\%RA = \frac{A_o - A_f}{A_o} \times 100$$

True stress & strain

Note: S.A. changes when sample stretched


□ True stress $\sigma_T = F/A_i$ $\sigma_T = \sigma(1 + \epsilon)$

□ True Strain $\epsilon_T = \ln(l_i/l_o)$ $\epsilon_T = \ln(1 + \epsilon)$



Hardening

- An increase in σ_y due to plastic deformation.



- Curve fit to the stress-strain response:


$$\sigma_T = K(\epsilon_T)^n$$

→ σ_T = "true" stress (F/A)
← ϵ_T = "true" strain: $\ln(L/L_0)$
← hardening exponent:
 $n = 0.15$ (some steels)
to $n = 0.5$ (some coppers)

5

Hardness









- Hardness: a measure of a material's resistance to localized plastic deformation or cracking in compression
- Simple and inexpensive
- Non destructive
- Can obtain other mechanical properties



Hardness tests

- Mohs scale: 1 talc < 2 Gypsum < 3 calcite < 4 fluorite < 10 diamond

Table 6.4 Hardness Testing Techniques

Test	Indenter	Shape of Indentation		Load	Formula for Hardness Number ^c
		Side View	Top View		
Brinell	10-mm sphere of steel or tungsten carbide			P	$HB = \frac{2P}{\pi D(D - \sqrt{D^2 - d^2})}$
Vickers microhardness	Diamond pyramid			P	$HV = 1.854P/d_1^2$
Knoop microhardness	Diamond pyramid			P	$HK = 14.2P/l^2$
Rockwell and Superficial Rockwell	<ul style="list-style-type: none"> ⎧ Diamond cone ⎩ 1/16, 1/8, 1/4, 1/2 in. diameter steel spheres 			<ul style="list-style-type: none"> 60 kg 100 kg 150 kg 15 kg 30 kg 45 kg 	<ul style="list-style-type: none"> Rockwell Superficial Rockwell

Hardness tests (continue)

- Rockwell and superficial rockwell
 - No major sample damage
 - Each scale runs to 130 but only useful in range 20-100.
 - Minor load 10 kg
 - Major load 60 (A), 100 (B) & 150 (C) kg
 - A = diamond, B = 1/16 in. ball
 - C = diamond

- Examples:
 - 80HRB, 60 HR30W

- 20 < hardness < 100

Table 6.5a Rockwell Hardness Scales


Scale Symbol	Indenter	Major Load (kg)
A	Diamond	60
B	1/16 in. ball	100
C	Diamond	150
D	Diamond	100
E	1/8 in. ball	100
F	1/16 in. ball	60
G	1/8 in. ball	150
H	1/16 in. ball	60
K	1/8 in. ball	150

Table 6.5b Superficial Rockwell Hardness Scales

Scale Symbol	Indenter	Major Load (kg)
15N	Diamond	15
30N	Diamond	30
45N	Diamond	45
15T	1/8 in. ball	15
30T	1/8 in. ball	30
45T	1/8 in. ball	45
15W	1/16 in. ball	15
30W	1/16 in. ball	30
45W	1/16 in. ball	45


Hardness tests (continue)

- Brinell: 10-mm sphere of steel or tungsten carbide
- Knoop and vickers microhardness
- Hardness conversion




Correlation between hardness and tensile strength

- Relations between hardness and tensile strength for steel, brass, and cast iron.
- For most steels:
 $TS \text{ (MPa)} = 3.45 \times HB$
 $TS \text{ (psi)} = 500 \times HB$



Example


- Estimate the Brinell and Rockwell hardnesses for brass and carbon steel



The stress-strain behavior for the brass specimen.

Example

- Estimate the Brinell and Rockwell hardnesses for brass and carbon steel



Tensile stress-strain behavior for a plain carbon steel

Variability of material properties

- Factors that lead to scatter in measured material properties
- The average

$$\bar{x} = \frac{\sum_{i=1}^n x_i}{n}$$

- The standard deviation

$$s = \left[\frac{\sum_{i=1}^n (x_i - \bar{x})^2}{n-1} \right]^{1/2}$$

where n is the number of data points



Example

- Determine the average and standard deviation of tensile strength

Sample Number	Tensile Strength (MPa)
1	520
2	512
3	515
4	522

$$\begin{aligned} \bar{TS} &= \frac{\sum_{i=1}^4 (TS)_i}{4} \\ &= \frac{520 + 512 + 515 + 522}{4} \\ &= 517 \text{ MPa} \end{aligned}$$

$$\begin{aligned} s &= \left[\frac{\sum_{i=1}^4 ((TS)_i - \bar{TS})^2}{4-1} \right]^{1/2} \\ &= \left[\frac{(520 - 517)^2 + (512 - 517)^2 + (515 - 517)^2 + (522 - 517)^2}{4-1} \right]^{1/2} \\ &= 4.6 \text{ MPa} \end{aligned}$$



Design/safety factors

- Design uncertainties mean we do not push the limit.
- **Factor of safety, N**

$$\sigma_{\text{working}} = \frac{\sigma_y}{N}$$

Often N is between 1.2 and 4

- **Ex:** Calculate a diameter, d, to ensure that yield does not occur in the 1045 carbon steel rod below. Use a factor of safety of 5.

$$\sigma_{\text{working}} = \frac{\sigma_y}{N}$$


$$\frac{220,000\text{N}}{\pi(d^2/4)}$$

5

1045 plain carbon steel:

$\sigma_y=310\text{MPa}$

TS=565MPa



F = 220,000N

Summary

- **Stress** and **strain**: These are size-independent measures of load and displacement, respectively.
- **Elastic** behavior: This reversible behavior often shows a linear relation between stress and strain. To minimize deformation, select a material with a large elastic modulus (E or G).
- **Plastic** behavior: This permanent deformation behavior occurs when the tensile (or compressive) uniaxial stress reaches σ_y .
- **Toughness**: The energy needed to break a unit volume of material.
- **Ductility**: The plastic strain at failure.